*model : VB-968A*

# *BOOT BAND CLAMPER*

- *In a class of its own when it comes to cutting! The blade can be simply removed, for easy access when re-grinding and replacing it.*
- *The length of the folded section can be adjusted for optimum cutting.*
- *The direction and angle of the cutter handle can be changed, a convenient feature for left-handed users.*



<<<<<<<< Precautions concerning usage of the VB-968A >>>>>>>>

<!> Check the instructions in the instruction manual provided by the maker for the work procedures, as well as the servicing guidelines for the vehicle. This unit cannot be used with genuine types of boot bands, or with caulking types that have tabs.

<!> If the band is wound too tightly, it may damage the boot. Be sure it is wound appropriately.

<!> The blade is a consumable item. If it reaches a point where it no longer cuts sharply, it should be re-ground or replaced with a spare one.

Usage method

(1) Pass the boot band which has been temporarily attached to the boot through the cutter section and the reel.

(2) Turn the reel to the right to wind the end of the band. When using a wrench, be careful not to tighten it too far.

(3) Checking that the band is appropriately tightened as you work, use this tool to fold the band back on itself.

(4) If the band has a projecting hook that is used to lock the folded section in place, return the wound band so that end of the band is aligned with that position, and then operate the cutter handle to cut the band.

(5) Use a hammer, punch, or similar tool to caulk the folded section.

MARKETING DIVISION
HASCO CO., LTD.
MANUFACTURE
HAYASHI SEIKO CO., LTD.
SALES DEPT. 3-6-45 SAKAE-CHO ASAKA-CITY SAITAMA 351-0012 JAPAN
TEL + 81-48-461-0101 FAX +81-48-461-1177

Issued Jan 2001 No.M968-E1